


## ATP-metry values interpretation - Ultra-pure water -



We consider that when a measurement is:

- Below the warning threshold (conformity), the facility is under control,

- Between the warning threshold and the alarm threshold (enhanced monitoring), the facility does not present an immediate biohazard. A corrective action is recommended if 3 consecutive measurements are above the warning threshold,

- Above the alarm threshold (corrective action), the facility is not under control. A quick corrective action is recommended (control, cleaning, disinfection...).