


Interpretation of ATP-metry values - Air -



We consider that when a measurement is:

- Below the warning threshold (conformity), the facility is under control,

- Between the warning threshold and the alarm threshold (**enhanced monitoring**), the facility does not present an immediate biohazard. A corrective action is recommended if 3 consecutive measurements are above the warning threshold,

- Above the alarm threshold (**corrective action**), the facility is not under control. A quick corrective action is recommended (control, cleaning, disinfection...).